

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**






FIG. 1A

FIG. 1B








FIG. 2




FIG. 3




FIG. 4




FIG. 5

Top view of a circular device. The central region is labeled 130, surrounded by concentric rings 132 and 134. The device has a flange 60 with four mounting tabs 62. Internal components include a central shaft 11, a ring 80, and a ring 110. A dashed line 114 indicates a cross-section. Other labels include 10, 13, 172, 82, and 66.

FIG. 6

106280-92808260




FIG. 7





FIG. 8






FIG. 10A




FIG. 11




FIG. 12

FIG. 13




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19